211318

งานวิจัยนี้คำเนินการภายในโรงงานกรณีศึกษาแห่งหนึ่งซึ่งเป็นบริษัทผู้ผลิตบรรจุภัณฑ์ พลาสติกหลากหลายรูปแบบ โดยมีผลิตภัณฑ์หลักคือถุงบรรจุผ้าอนามัย จากการสำรวจพบว่า กระบวนการที่สำคัญและมีส่วนเกี่ยวข้องกับคุณภาพของผลิตภัณฑ์มากที่สุด คือ กระบวนการพิมพ์ ซึ่งมี ชื่อเรียกว่า กระบวนการพิมพ์กราเวียร์ ปัญหาหลักของกระบวนการพิมพ์กราเวียร์ คือ มีของเสียเกิดขึ้น เป็นจำนวนมากถึง 25-45%

วัตถุประสงค์ของงานวิจัยนี้ คือ เพื่อหาสาเหตุหลักของปัญหาคุณภาพในกระบวนการพิมพ์ บรรจุภัณฑ์พลาสติก และพัฒนาวิธีการปรับปรุงคุณภาพเพื่อลดของเสียโดยประยุกต์ใช้เทคนิคทาง คุณภาพ ได้แก่ กราฟ แผนภาพการกระจาย แผนผังแสดงสาเหตุและผล แผนภาพพาเรโต แผนผังกลุ่ม เชื่อมโยง แผนผังต้นไม้ การออกแบบการทดลอง และแผนภูมิควบคุม ซึ่งในระหว่างการดำเนินงานวิจัย นั้นผู้วิจัยได้มีการจัดตั้งทีมงานสำหรับปรับปรุงคุณภาพของโรงงาน และเป็นผู้มีส่วนร่วมในการพัฒนา ปรับปรุงคุณภาพของโรงงาน

ขั้นตอนการคำเนินงานวิจัยนี้ประกอบไปด้วย 5 ระยะ ได้แก่ (1) ระยะการกำหนดปัญหาได้ทำ การคัดเลือกปัญหาที่จะทำการวิเคราะห์หาสาเหตุและแนวทางการแก้ไข คือ ปัญหาการพิมพ์เบี้ยวใน กระบวนการพิมพ์ถุงบรรจุผ้าอนามัยที่ผลิตจากวัตถุดิบแผ่น PE นม ขนาด 0.04 มิลลิเมตร รหัสสินก้า A018 จากเครื่องพิมพ์ PR10 (II) ระยะการหาสาเหตุหลักของปัญหา พบว่า สาเหตุหลักของปัญหาที่จะ นำไปหาวิธีการแก้ไข ได้แก่ (1) ระตบอุณหภูมิบนเครื่องพิมพ์ไม่เหมาะสม (2) แรงตึงของม้วนฟิล์มไม่ เหมาะสม (3) พนักงานขาดการฝึกอบรมวิธีการทำงาน และ (4) การขาดการบำรุงรักษาเชิงป้องกัน (III) ระยะการหาวิธีการแก้ปัญหาประกอบด้วย 2 วิธี คือ การออกแบบการทดลอง และการสร้างระเบียบ วิธีการปฏิบัติงานในกระบวนการพิมพ์ ผลจากการออกแบบการทดลองทำให้ทราบถึงก่าของการปรับตั้ง ปัจจัย ได้แก่ อุณหภูมิของส่วนพิมพ์ที่ 7 มีค่าเท่ากับ 50°C อุณหภูมิของส่วนพิมพ์ที่ 8 มีค่าเท่ากับ 50°C และแรงดึงของม้วนฟิล์มมีค่าเท่ากับ 15 N/mm. (IV) ระยะการนำวิธีการแก้ปัญหาไปปฏิบัติได้ดำเนินการ ตามแผนงานที่ได้กำหนดไว้ (V) ระยะการประเมินผลพบว่า สามารถทำให้เปอร์เซ็นต์ ตามลำดับ และเวลาใน เบี้ยวเฉลี่ยและเปอร์เซ็นต์ของเสียรวมเฉลี่ยลดลง 14.94 และ 12.71 เปอร์เซ็นต์ ตามลำดับ และเวลาใน การพิมพ์งาน A018 ลดลงเฉลี่ย 8.87 นาทีต่อม้วน This research was carried out in a flexible packaging manufacturer which produces various plastic packaging and sanitary bag. The preliminary survey indicated that the printing process, named the gravure printing process, had the most impact to company product quality. The main problem of gravure printing process was its high percentage of defect up to 25-45 percent.

The purpose of this study is to find the root causes of the quality problem in plastic packaging printing process and develop a quality improvement approach for defect reduction by using quality techniques including graph, scatter diagram, cause-and-effect diagram, pareto diagram, affinity diagram, tree diagram, design of experiment, and control chart. During this study, a quality improvement team has been set and work closely with this quality improvement project.

The methodology was composed of five phase. Phase I, Quality problem definition, which indicated that the quality problem focused in this thesis was the overlapping printing problem (coded A018). Code A018 was a problem of a sanitary bag product produced of white PE plastic film of 0.04 millimeters thickness from printing machine coded PR10. Phase II, Root causes identification, revealed root causes of (1) improper temperature level on heaters of the print unit, (2) the improper web tension, (3) the lack of adequate training for operators, and (4) the lack of preventive maintenance. Phase III, Problem-solving generation was composed of two alternatives were the design of experiment on three factors (temperature on print unit no.7 and 8, and web tension) and development of work instruction. Results from the design of experiment indicated that the appropriate levels of these three factors were the 50°C temperature level on both print unit no.7 and 8, and the 15 N/mm. of web tension. Phase IV, Selection of alternative application was the implementation of action plan generated from previous phase. Phase V, Evaluated results from the implementation, which found that the percentage of average overlapping printing defect and average total defect decreased 14.94 and 12.71 percent respectively, and the average printing time decreased 8.87 minutes per roll.