วิทยานิพนธ์ฉบับนี้มีวัตถุประสงค์เพื่อทำการวิเกราะห์การเกิดอัคคีภัยที่เกิดจากก๊าซหุงต้ม ในร้านอาหารที่มีลักษณะเป็นการเคินแนวท่อก๊าซเข้ามาภายในห้องครัวของร้าน โดยอาศัยทฤษฎี และหลักการทางวิศวกรรมความปลอดภัยมาประยุกต์ใช้ในการนำเสนอมาตรการทางค้านความ ปลอดภัย โดยในการวิเกราะห์ครั้งนี้ใช้โปรแกรมภาพเสมือนในการจำลองเหตุการณ์เพลิงใหม้ (Fire Dynamics Simulation, FDS) จำลองการเกิดเพลิงใหม้ที่เกิดจากการรั่วของก๊าซหุงต้ม ในการศึกษานี้จะดูการกระจายตัวของเพลิงและควันไฟ และศึกษาผลของการออกแบบระบบป้องกัน และระงับอัคคีภัยสำหรับร้านอาหาร

โดยผลจากการวิเคราะห์รูปแบบการกระจายตัวของเพลิงและทิสทางของการเกลื่อนที่ของ ควันภายในร้านอาหารหากไม่มีการติดตั้งระบบป้องกันและระงับอักคีภัย พบว่าเพลิงใหม้ที่เกิด จากก๊าซหุงต้มจะเกิดการเผาไหม้ไปอย่างต่อเนื่อง และมีควันกระจายตัวออกมารอบๆ ในบริเวณ ร้าน และผลจากการติดตั้งระบบป้องกันและระงับอักคีภัยที่เหมาะสมกับประเภทของพื้นที่ตาม มาตรฐานของสมากมวิสวกรรมสถานแห่งประเทศไทย ในพระบรมราชูปถัมภ์ (2545, 2548) โดย การติดตั้งหัวกระจายน้ำดับเพลิงจำนวน 4 หัว พบว่าระบบจะเริ่มทำงานที่เวลา 5 นาที ซึ่งจะทำให้ เพลิงค่อยๆ ดับลง แต่เมื่อทำการติดตั้งอุปกรณ์ตรวจจับกวามร้อนร่วมกับการติดตั้งระบบหัว กระจายน้ำดับเพลิง โดยติดตั้งจำนวน 5 หัว พบว่าอุปกรณ์ตรวจจับกวามร้อนจะเริ่มทำงานก่อน ระบบหัวกระจายน้ำดับเพลิง โดยทำงานที่เวลาเพียง 82.4 วินาที และหลังจากอุปกรณ์ตรวจจับ ความร้อนทำงานได้กำหนดให้ส่งสัญญาณไปตัดระบบการส่งจ่ายก๊าซที่บริเวณเตาก๊าซ ซึ่งทำให้ เพลิงคับลงในทันที

184582

This research aimed to analyses the fire protection of liquefied petroleum gas fire occurrence in restaurants, having gas pipe line connected to the kitchens. According to engineering safety theory and principle, safety guidelines suggested by Fire Dynamics Simulation (FDS) are proposed. The fire caused from the cooking gas leaking was simulated. In this study, fire and smoke distribution were performed. The results of safety system after installing in the restaurant were also studied.

The simulation results of the fire distribution and smoke moving direction in the restaurant (no safety system was installed) revealed that fire combustion was continue and smoke distributed around the restaurant. However, after the 4 sprinkler were installed according to the Engineering Institute of Thailand under H.M. the King's Patronage standard (2545, 2548), the sprinkler worked after 5 minutes of fire and the fire gradually stopped. If 5 sprinkler were installed, heat detector started to alarm and sprinkler worked after 82.4 seconds. Then the gas pipe line was cut off and the fire stopped.