

งานวิจัยนี้ศึกษาการหล่อแข็งโลหะไฮดรอกไซด์โดยใช้วัสดุชีดประสานประเภทปูนขาวและซีเมนต์แก้วที่ไวต่อการทำปฏิกิริยาเป็นวัสดุชีดประสานในสภาวะที่มีและไม่มีการกระตุ้นปฏิกิริยาของวัสดุชีดประสานด้วยสารเคมี ได้แก่ โซเดียมคาร์บอเนต( $\text{Na}_2\text{CO}_3$ ), โซเดียมซิลิเกต( $\text{Na}_2\text{SiO}_3$ ) และปูนซีเมนต์ผลการทดสอบการพัฒนากำลังรับแรงอัดของซีเมนต์ผสม พบว่า ส่วนผสมระหว่างปูนขาวและซีเมนต์แก้วเท่ากัน 45:55 ในสภาวะที่มี 8% โซเดียมคาร์บอเนตหรือ 8% โซเดียมซิลิเกต มีการพัฒนากำลังอัดได้ดีกว่าที่อัตราส่วนอื่น จากนั้นจึงทำการเติมตะกรอนโลหะไฮดรอกไซด์สังเคราะห์ 3 ชนิด คือ สังกะสี, โคโรเมียม และเหล็ก ที่อัตราส่วนร้อยละ 10 โดยนำหนัก พบว่า ความสามารถในการรับแรงอัดของก้อนหล่อแข็งของเสียที่อายุ 28 วันมีค่าผ่านค่ามาตรฐานสำหรับการฝังกลบแบบปลอดภัย นอกจากนี้ยังพบว่า สังกะสีไฮดรอกไซด์หน่วงปฏิกิริยาไฮเดรชันของวัสดุชีดประสานส่งผลให้ระบบเวลาการก่อตัวเริ่มต้นและสุดท้ายเพิ่มขึ้น และการทดสอบการรั่วไหลของโลหะหนักโดยวิธี TCLP พบว่า ความเข้มข้นของโลหะหนักทุกตัวในสารละลายสักด้อยู่ในระดับที่ไม่เกินเกณฑ์มาตรฐานที่กำหนด

## Abstract

TE150822

This research work investigated the solidification of metal hydroxides using hydrated lime and reactive rice husk ash (rRHA) with and without chemical activators as solidification binders. Sodium carbonate ( $\text{Na}_2\text{CO}_3$ ), sodium silicate ( $\text{Na}_2\text{SiO}_3$ ) and ordinary Portland cement (OPC) were used as activators. Strength development of the blended cements were tested. Results showed that the mixes between hydrated lime and rRHA of 45:55 with 8%  $\text{Na}_2\text{CO}_3$  or  $\text{Na}_2\text{SiO}_3$  have higher rate of strength development than other mixes. Three synthetic metal hydroxides,  $\text{Zn}(\text{OH})_2$ ,  $\text{Cr}(\text{OH})_3$ , and  $\text{Fe}(\text{OH})_3$ , were then added at 10 wt.% to the above mixes. It was found that the 28-day compressive strength of the solidified wastes meets the minimum requirement for secure landfill. In addition,  $\text{Zn}(\text{OH})_2$  was observed to retard the hydration reactions of the binders. Concentration of all heavy metals in the leachate was not exceeded the standard of TCLP.