การวิจัยครั้งนี้มีวัตถุประสงค์เพื่อศึกษาปัจจัยที่ส่งผลต่อความเรียบผิวในการกลึงเหล็กแม่พิมพ์งานเย็น เกรด DC 53 โดยเทียบกับคุณภาพผิวของงานเจียรนัยเป็นเกณฑ์ ด้วยมีดกลึงอินเสิร์ทลาร์ไบด์เคลือบ ผิวด้วยกระบวนการพีวีดี (PVD-coated with Titanium Aluminum Nitride) ปัจจัยที่ใช้ในการศึกษาคือ ความเร็วตัด อัตราป้อนและ ระยะป้อนลึก โดยการออกแบบการทดลองแบบแฟกทอเรียล ผลการ ทดลองพบว่าปัจจัยที่ส่งผลต่อความเรียบผิวคือ ปัจจัยร่วมระหว่างตัวแปร อัตราป้อน ระยะป้อนลึก และอัตราป้อนซึ่งมีผลต่อคุณภาพของผิวงานอย่างมีนัยสำคัญที่ระดับ .01 โดยที่อัตราป้อนในระดับต่ำ จะให้ความเรียบผิวของผิวงานที่ดี แต่เมื่อเพิ่มอัตราป้อนที่มีระดับสูงขึ้นจะส่งผลต่อความเรียบผิวของ ผิวงานต่ำลง จากการวิเคราะห์สมการถดลอยพบว่าอัตราป้อนเป็นตัวระบุลึงอิทธิพลของที่มีต่อค่าความ เรียบของผิวงาน ผลการทดลองพบว่าปัจจัยที่ส่งผลต่อความสึกหรอของเครื่องมือตัดคือ ปัจจัยร่วม ระหว่างตัวแปร อัตราป้อน ระยะป้อนลึก และอัตราป้อนซึ่งมีผลต่อคุณภาพของผิวงานอย่างมี นัยสำคัญที่ระดับ .01 โดยที่อัตราป้อนในระดับต่ำจะให้ค่าความสึกหรอของเครื่องมือตัดที่น้อย แต่ เมื่อเพิ่มอัตราป้อนที่มีระดับสูงขึ้นจะส่งผลต่อค่ากวามความสึกหรอของเครื่องมือตัดสูงขึ้น

## 225320

The purpose of this research was to study factors affecting the surface roughness in Cold work steels (DC53) turning by comparing it to the surface quality of grinding work set as criterion using inserted carbides surface cutting tools coated with Physical Vapor Deposition (PVD-coated with Titanium Aluminum Nitride) process. Factors studied were consisted of cutting speeds, feed rates, and depth of cuts applying factorial design. Results revealed that interaction factor of cutting speeds, feed rates and depth of cuts was affected to surface roughness of cold work steels turning significantly different at the level of .01. Moreover, the result on feed rate showed that low level of feed rate would provide better surface roughness than high level of feed rate. Predicted roughness of surface using regression equation was identified to relation of feed rate for roughness. Finally, feed rate was significantly affected to mill wear at the level of .01 and when increasing feed rate, the tool wear was be increased.