

บรรณานุกรม

- [1] D. Cope Enterprises, "On-Board Diagnostics II (OBDII) and Light-Duty Vehicle Emission Related Inspection and Maintenance (I/M) Programs," Transportation Systems Branch, Environment Canada, Apr. 2004.
- [2] C. Bettstetter *et al.*, "GSM phase 2+ General Packet Radio Service GPRS: Architecture, Protocols, and Air interface," *IEEE Communications Survey*, vol. 2, no. 4, 1999.
- [3] I. Aris, M.F. Zakaria, S.M. Abdullah, R.M Sidek, "DEVELOPMENT OF OBD-II DRIVER INFORMATION SYSTEM", *FEIIC International Journal of Engineering and Technology*, vol. 4, no. 2, pp. 253-259, 2007.
- [4] Lin, C.E., Chih-Ching Li, Chih-Chen Wu, Liu, H.S., Tseng, M.Y., "A real time GPRS surveillance system using the embedded system," *Industrial Electronics Society, 2003. IECON '03. The 29th Annual Conference of the IEEE* , vol.2, pp. 1228-1234, 2-6 Nov. 2003.
- [5] Lin, C. E., Shiao, Y.-S., Li, C.-C., Yang, S.-H., Lin, S.-H., Lin, C.-Y., "Real-Time Remote Onboard Diagnostics Using Embedded GPRS Surveillance Technology," *Vehicular Technology, IEEE Transactions on* , vol.56, no.3, pp.1108-1118, May 2007.
- [6] Song You, Mark Krage, Laci Jalics, "Overview of Remote Diagnosis and Maintenance for Automotive Systems," SAE Technical paper series 2005-01-1428, 2005 SAE World Congress, Detroit, Michigan, 11-14 Apr. 2005.
- [7] Arvon L. Mitcham, "On-Board Diagnostic Hand-Held Scan Tool Technology: Adherence to the Society of Automotive Engineers Requirements for Scan Tools and an Evaluation of Overall Scan Tool Capability," Technical Report EPA420-R-00-017, Environmental Protection Agency (EPA), U.S., Oct. 2000.
- [8] Robert Bosch GmbH, "CAN Specification, Version 2.0," Stuttgart, Germany, Sep. 1991.

- [9] H. Boterenbrood, "CANopen high-level protocol for CAN-bus," Version 3.0, NIKHEF, Amsterdam, 20 March 2000.
- [10] International Organization for Standardization, "ISO/DIS 15765-4.2," 6 April 2003
- [11] T. Berners-Lee, R. Fielding and H. Frystyk, "Hypertext Transfer Protocol – HTTP/1.0," IETF RFC 1945, May 1996.
- [12] PHP [Online]. Available: <http://www.php.net>
- [13] Holox Technology Inc., "HOLUX GR-82 GPS Engine Board User's Guide ,," Version A, 29 May 2006
- [14] Microchip Technologies Inc., "PIC18F2X8X Datasheet," 2004.
- [15] Microchip Technologies Inc., "MCP2551 Datasheet," 2002
- [16] K. Tindell, A. Burns, "Guaranteeing Message Latencies on Controller Area Network (CAN)," Proceedings 1st International CAN Conference, Mainz (Germany), Sep 1994
- [17] Future Technology Devices International Ltd., "FT232R USB UART I.C. Datasheet," 2005
- [18] Elm Electronics, "ELM327 OBD to RS232 Interpreter"
- [19] Dallas Semiconductor, "DS1307 64 x 8 Serial Real-Time Clock Datasheet"
- [20] Wavecom, "Integrators Manual GS64 GSM/GPRS Wireless CPU," 19 Sep 2006
- [21] P. Lynch, "Nokia 6100 LCD Display Driver," Revision 1
- [22] MySQL [Online]. Available: <http://www.mysql.com>