

ยสินธรา ชาทอง : แนวทางการพัฒนาภูมิทัศน์มหาวิทยาลัยขอนแก่น.

(GUIDELINES FOR LANDSCAPE DEVELOPMENT OF KHONKAEN

UNIVERSITY) อ.ที่ปรึกษา : รองศาสตราจารย์ นิรุบล คล่องเวสสะ, จำนวน

หน้า 128 หน้า. ISBN 974-53-1624-5

งานวิทยานิพนธ์มีจุดมุ่งหมายในการศึกษาแนวทางการพัฒนาภูมิทัศน์มหาวิทยาลัยขอนแก่น โดยศึกษาปัญหาปัจจุบันของสภาพภูมิทัศน์มหาวิทยาลัยขอนแก่น และปัจจัยในการออกแบบภูมิทัศน์มหาวิทยาลัยขอนแก่น เพื่อเสนอแนวทางในการพัฒนาภูมิทัศน์มหาวิทยาลัยขอนแก่น

การศึกษาแบ่งออกเป็น 4 ขั้นตอน คือ ขั้นตอนที่ 1 การศึกษาข้อมูลจากผังแม่บทและเอกสารที่เกี่ยวข้อง เพื่อศึกษาหาปัญหาที่เกิดขึ้น ขั้นตอนที่ 2 การลงสำรวจพื้นที่เพื่อสังเกตการณ์ในเรื่องพฤติกรรมการใช้พื้นที่ของนักศึกษาและบุคลากรในมหาวิทยาลัย และปัญหาทางกายภาพ ขั้นตอนที่ 3 ทำการสอบถามโดยการแจกแบบสอบถามกับนักศึกษาและบุคลากรภายในมหาวิทยาลัยถึงปัญหาในเรื่องพฤติกรรมในการใช้งานและความต้องการในการพัฒนาภูมิทัศน์มหาวิทยาลัยขอนแก่น ขั้นตอนที่ 4 สรุปปัญหาปัจจุบันที่เกิดขึ้นของภูมิทัศน์มหาวิทยาลัยขอนแก่น ปัจจัยที่มีผลต่อการออกแบบภูมิทัศน์มหาวิทยาลัยขอนแก่นและเสนอแนวทางการพัฒนาภูมิทัศน์มหาวิทยาลัยขอนแก่น

ผลการศึกษาพบว่า มหาวิทยาลัยขอนแก่นมีแนวแกนหลัก คือ ถนนมหาวิทยาลัยขอนแก่นหมายเลข 1 ซึ่งควรพัฒนาให้เกิดเอกลักษณ์ที่ชัดเจนขึ้น ด้านการสัญจร ถนนยังขาดร่มเงา ทางเดินเท้าขาดความต่อเนื่องและแสงสว่างไม่เพียงพอ ที่จอดรถมีความต้องการให้การเดินเข้าสู่อาคารสะดวก ระยะทางสามารถห่างออกไปได้อีกสำหรับพื้นที่เปิดโล่ง การเข้าถึงไม่ชัดเจนและพื้นที่ไม่สะดวกต่อการใช้งานต้องมีการพัฒนาภูมิทัศน์

4474196025 : MAJOR LANDSCAPE

KEYWORD : Campus Planning / Campus Landscape / Circulation System / Open Space System

YASINTARA CHARTHONG : GUIDELINES FOR LANDSCAPE DEVELOPMENT OF KHONKAEN UNIVERSITY. THESIS ADVISOR : ASSOC PROF. NILUBON KLONGVESSA, 124 pp. ISBN 974-53-1624-5

This study work has the objective to study a guideline for landscape development of Khonkaen University by studying the current problems of Khonkaen University in order to present a guideline for landscape development of Khonkaen University.

The study was divided into 4 steps. The 1st step is a study of the information from the master plan in order to study the problems. The 2nd step is to make the site survey in order to observe the behavior of the utilization of the place by the students and personnel in the University and the physical problems. The 3rd step is to make inquiries by distributing the questionnaires to the students and the personnel concerning the problems of the behavior in using the place. The 4th step is to summarize the current problems occurring of the landscape of Khonkaen University. The factors which have the effects upon the designing the landscape of Khonkaen university and a proposal of the guideline for landscape development of Khonkaen University.

From the result of the study, it was found that Khonkaen University has the main core which included Road 1 which should be developed to be more unique on the traffic. The street still lacks shades. The walkways still lack continuity and the lighting is not sufficient. The car park still needs convenient entrance into the buildings. The walking distance can be further out. For the open space, it was found the access is not clear and not convenient for utilization. Landscapes must be developed.