

T 145506

งานวิจัยนี้เป็นการศึกษาเพื่อปรับปรุงระบบบำบัดน้ำเสียเดิมของโรงพยาบาล โดยใช้ระบบເອສນີອາຣ໌ແບນກົງດ່ວຍເນື່ອງ ພວກວ່າโรงพยาบาลທີ່ສຶກໜາມີນ້ຳເສີບຄູ່ 5 ແຫລ່ງດໍາເນີດ ຄື້ອ ນ້ຳເສີບຈາກ 2 ອາຄາຣ, ນ້ຳເສີບຈາກ 2 ໂຮງອາຫາຣ ແລະນ້ຳຊັກຜ້າ ໂດຍມີນ້ຳເສີບຈາກອາກາຣເພື່ອການເດືອນທີ່ເກີດໃຫຍ່ເຖິງການເປັນເຂົ້າຮັບນ້ຳເສີບຈາກໄຮ້ອາກາສແບນຕຽງພິລົມຊື່ເປັນຮະບນນໍາບັດເດີມຂອງໂຮງພຍານາລ ແລະນ້ຳທີ່ອອກຈາກຮະບນນໍາບັດຍັງໄມ່ພ່ານຕາມຄໍາມາຕຽບຖານທີ່ກໍາທັນດ

การปรับปรุงຮະບນນໍາບັດຈາກຮະບນໄຮ້ອາກາສມາເປັນຮະບນເອສນີອາຣແບນກົງດ່ວຍເນື່ອງ ໂດຍຈະນໍານ້ຳເສີບຈາກທຸກແຫລ່ງດໍາເນີມາເຂົ້າຮັບນໍາບັດ ແລະດ້ອງນີ້ການສ່ວນງ່ອດັກໄຟມັນເພີ່ມສໍາຫຼັບນ້ຳເສີບຈາກໂຮງອາຫາຣທີ່ 2 ແລະສ່ວນບ່ອພັກນ້ຳສໍາຫຼັບການຮັດກັນນ້ຳຊັກຜ້າທີ່ປັນເປັນເປື້ອນສາງຄລອຣິນດ້ວຍສາຮລາຍໄຊເຕີບນໄໂຫໂອຊັດເຟເຂັ້ມື້ນ 2 ເປົ່ອຮັ້ນຕໍ່ໂຄບນ້ຳໜັກດ່ວຍປຣິມາຕຣ ໂດຍຄວນຄຸມຄ່າຄວາມຕ່າງສັກຍົ່ງອອກຊີເຄັນ-ຮັດກັນເປັນ 350 ມິລິლໄວລຕໍ່ກ່ອນເຂົ້າສູ່ນໍ່ປ່ອບປ່ອບເສດີຍ ຈາກການສຶກໜາພົນວ່າມີຄໍານີ້ໂອດີ, ກໍາຄົງທີ່ອັຕຣາງອົງປົງກົງກິຣິຂາ (K) ແກະໄວຣິນາທຣນໍ້ອເອສນີອາຣແບນກົງດ່ວຍເນື່ອງເປັນ 150 ມກ./ລ., 0.078 ແລະ 75.2 ລບ.ມ. (ໄນ່ຮົວມິນິໂຮງຮົດ) ດາວັນດໍາດັບ ສໍາຫຼັບສກວະທີ່ເໝາະສົມດ່ອກການທຳການຂອງຮະບນເອສນີອາຣແບນກົງດ່ວຍເນື່ອງພົນວ່າທີ່ຮະບະເວລາເດີມອາກາສ-ເດີມນ້ຳເສີຍເປັນ 3 ຊົ່ວໂມງ, ຮະບະເວລາຕົກຕະກອນເປັນ 1 ຊົ່ວໂມງ ແລະຮະບະເວລາປ່ອບ່ອນ້ຳໃສອອກເປັນ 50 ນາທີ ສາມາດນໍານັບນ້ຳເສີບຂອງໂຮງພຍານາລໄຫ້ພ່ານຕາມທີ່ມາຕຽບຖານກໍາທັນດໄວ້ໄດ້

Abstract

TE 145506

This work involved development of the wastewater treatment system in the hospital by using cyclic-SBR. There are 5 lines of wastewater; from the two buildings, from the two canteens and from laundry. The old fixed-film plant treated the wastewater from only one building. The treated wastewater was not complied with the standard.

Development of the old fixed-film anaerobic system to cyclic-SBR by constructing grease and oil trap tank for the second canteen wastewater and another tank for chlorine reduction of laundry wastewater. The reduction by using 2% (w/v) sodiumthiosulphate solution and on-line controlling oxidation-reduction potential at 350 mV before passing through the equalization tank. The studied BOD_5 , the reaction rate constant (K) and the capacity of cyclic-SBR tank were 150 mg/l, 0.078 and 75.2 m^3 (excluded freeboard) respectively. All of the wastewater sources now, flow through the wastewater treatment system. From study, the suitable treatment cycle consisted of 3 hours for fill-aeration, 1 hour for settling and 50 minutes for decanting. The effluent qualities of the new plant are now complied with the standard.