ควงนภา วานิชสรรพ์ 2551: การศึกษาผลกระทบของน้ำทิ้งจากฟาร์มเลี้ยงสุกรในเขตจังหวัคราชบุรี ที่มีต่อคุณภาพน้ำและการบริหารจัคการน้ำ ในเขตฝั่งตะวันตกของแม่น้ำแม่กลอง ปริญญาวิศวกรรม ศาสตรมหาบัณฑิต (วิศวกรรมชลประทาน) สาขาวิศวกรรมชลประทาน ภาควิชาวิศวกรรมชลประทาน อาจารย์ที่ปรึกษาวิทยานิพนธ์หลัก: รองศาสตราจารย์สันดิ ทองพำนัก, M.Eng. 195 หน้า

การศึกษานี้มีวัตถุประสงค์เพื่อศึกษาผลกระทบของน้ำทิ้งจากฟาร์มเลี้ยงสุกรต่อคุณภาพน้ำในแหล่งน้ำ ธรรมชาติ โดยเก็บตัวอย่างน้ำ ณ บริเวณ คลองทับแถบ คลองระบายน้ำสาย 4R, 5R, 6R, 7R ประคู่ (ตำแหน่ง บรรจบคลองประคู่) ด้านเหนือน้ำและด้านท้ายน้ำคลองประคู่ ในช่วงระหว่างเดือนพฤษภาคม พ.ศ. 2549 ถึง เดือนสิงหาคม พ.ศ. 2549 และเดือนกุมภาพันธ์ พ.ศ. 2550 ถึงเดือนพฤษภาคม พ.ศ. 2550 นอกจากนี้ยังได้ ทำการศึกษาทางด้านชลศาสตร์ การแพร่กระจายของมวลสารในน้ำ และคุณภาพน้ำของคลองประคู่ โดยใช้ แบบจำลองทางคณิตศาสตร์ MIKE 11

ผลการวิเคราะห์คุณภาพน้ำพบว่า คุณภาพน้ำโดยรวมในคลองประคู่ ณ ตำแหน่งต่างๆ อยู่ในเกณฑ์ มาตรฐานแหล่งน้ำธรรมชาติ ในขณะที่คัชนีคุณภาพน้ำบางประการมีค่าสูงกว่ามาตรฐาน คือ ค่าความต้องการ ออกซิเจนทางชีวเคมี (BOD) ค่าการนำไฟฟ้า (EC) และปริมาณของแข็งทั้งหมดที่ละลายในน้ำ (TDS) จึงพอสรุป ได้ว่า ปริมาณน้ำท่าจากคลองระบาย ปริมาณน้ำในคลองประคู่ และพฤติกรรมการปล่อยน้ำจากฟาร์มเลี้ยงสุกร ส่งผลต่อคุณภาพน้ำในคลองประคู่ ซึ่งสังเกตได้ว่าบริเวณที่มีการเลี้ยงสุกร คุณภาพน้ำที่ได้ค่อนข้างต่ำกว่าเกณฑ์ มาตรฐาน ทำให้ทราบว่าของเสียจากฟาร์มสุกรมีผลกระทบต่อคุณภาพน้ำในแม่น้ำค่อนข้างชัดเจน แต่บริเวณสิ้นสุด ของคลอง ซึ่งเป็นแหล่งรวมของปริมาณน้ำทั้งหมดและได้รับน้ำที่มีคุณภาพคืจากแม่น้ำแควอ้อม คุณภาพน้ำที่ได้ อยู่ในเกณฑ์มาตรฐาน

ผลการประยุกต์ใช้แบบจำลอง MIKE 11 พบว่า ในการสอบเทียบแบบจำลองเพื่อหาค่าพารามิเตอร์ ที่เหมาะสม ได้ค่าสัมประสิทธิ์ความขรุขระที่ท้องลำน้ำของแบบจำลองย่อยอุทกพลศาสตร์มีค่าอยู่ระหว่าง 0.025 – 0.029 ค่าสัมประสิทธิ์การแพร่กระจายของแบบจำลองย่อยการพา - แพร่กระจายมีค่าอยู่ระหว่าง 10-25 ตารางเมตร/วินาที และค่าสัมประสิทธิ์ของแบบจำลองย่อยคุณภาพน้ำซึ่งประกอบด้วย ค่าสัมประสิทธิ์การย่อยสลาย สารอินทรีย์มีค่าเท่ากับ 0.2 วัน อีตราการผลิตออกซิเจนสูงสุดจากการสังเคราะห์แสงของพืชมีค่าเท่ากับ 3.5 กรัม ออกซิเจน/ตารางเมตร/วัน และอัตราการหายใจของพืชและสัตว์น้ำมีค่าเท่ากับ 1 กรัม ออกซิเจน/ตารางเมตร/วัน จากการศึกษายังพบว่า ในช่วงเดือนพฤษภาคมมีปัญหาทางด้านคุณภาพน้ำต่ำกว่ามาตรฐาน ดังนั้นจึงมีความจำเป็น ที่จะต้องทำการควบคุมเพื่อลดการปล่อยของเสียจากฟาร์มเลี้ยงสุกร และเฝ้าระวังในเรื่องของคุณภาพน้ำ รวมทั้ง ตรวจวัดคุณภาพน้ำ อนึ่งหากมีปัญหาคุณภาพน้ำต่ำกว่ามาตรฐานในคลองระบาย ควรแก้ปัญหาเฉพาะหน้าโดย การปล่อยน้ำลงคลองระบายน้ำเพิ่มเติม เพื่อไล่ของเสียออกจากระบบ

ดาวงานภา อาค์มชงงาพั

ลายมือชื่อนิสิต

ลายมือชื่ออาจารย์ที่ปรึกษาวิทยานิพนธ์หลัก

10,03,257

Duangnapa Vanichsan 2008: The Study on Effect of Swine Farm Sewage in Ratchaburi Province

to Water Quality and Water Management in the Western Side of Mae Klong River. Master of

Engineering (Irrigation Engineering), Major Field: Irrigation Engineering, Department of Irrigation

Engineering. Thesis Advisor: Associate Professor Santi Tongpumnuk, M.Eng. 195 pages.

This study aims to evaluate the impact on water quality caused by the sewage from the swine farm

by examining the water sample in Klong Thaptab, Sub-Drain 4R, 5R, 6R, 7R of Klong Pradue (near its outlet

to Klong Pradue) and upstream and downstream of Klong Pradue during May, 2006 to August, 2006 and

February, 2007 to May, 2007. Moreover, the MIKE 11 Model was applied in Klong Pradue for studying the

hydraulic characteristic, advection-dispersion process and water quality.

The result showed that the overall water quality in Klong Pradue at all locations were within the

standard of natural water resources. However, some water quality indices were higher than the standard such

as BOD, EC and TDS. It may conclude that surface runoff, flow in Klong Pradue and the sewage released

from swine farm may affect water quality in Klong Pradue. Moreover, it can be clearly seen that the water

quality at the location near the swine farm is lower than the standard, and water quality improves continuously

at the downstream location especially at the outlet to river (the downstream end of Klong Pradue) since it

receives some water with good quality from Kwae - Om River. Therefore the sewage from swine farm has a

direct impact on water quality in the river.

The result from the model calibration of MIKE 11 showed that appropriate value for Manning's n

of hydrodynamic module were 0.025-0.029, the dispersion coefficient of advection-dispersion module were

10 - 25 m<sup>2</sup>/s. The coefficients of water quality module were as follows: BOD decay coefficient was 0.2 day<sup>-1</sup>,

maximum oxygen production by photosynthesis was 3.5 g O<sub>2</sub>/m<sup>2</sup>/day, and oxygen consumption by respiration

of plant and animal was 1 g O<sub>2</sub>/m<sup>2</sup>/day. In addition it is found that the water quality is lower than the standard

in May so the sewage release from the swine farm should be controlled and the water quality should be carefully

monitored during this critical time. Once there is a problem of low water quality, the extra release through the

drainage system may be implemented to improve the water quality.

Thesis Advisor's signature